






1

2




3



A  $\varnothing=6\text{MM}$ $H=36\text{MM}$ $\times 22$	B  $\varnothing=15\text{MM}$ $H=10\text{MM}$ $\times 22$	C  $\varnothing=6\text{MM}$ $H=30\text{MM}$ $\times 12$
D  $\varnothing=4\text{MM}$ $H=40\text{MM}$ $\times 14$	E  $\varnothing=4\text{MM}$ $H=12\text{MM}$ $\times 18$	F  $43*16*14\text{mm}$ $\times 1$
G  $\times 1$	H  $\times 2$	I  $\varnothing=4\text{MM}$ $H=15\text{MM}$ $\times 2$


1

H		x2
E		x6
G		x1
A		x8




2

D		x8
---	---	----




3

B		x8
---	---	----




4

A		x6
---	---	----




5

A		x4
E		x4




6

A		x4
E		x4
F		x1
I		x2




7

B		x4
C		x4




8


B		x4
C		x4



9




10




11

D  x5




12

B  x2
D  x1




13

B		x4
C		x4




14

E		x4
----------	---	----



15



16

